DI2YP-03

DTC	C2943/403	Auxiliary Battery Voltage Abnormally Low
	323 19, 199	· · · · · · · · · · · · · · · · · · ·

CIRCUIT DESCRIPTION

During the drive mode, or while charging with the normal charge, charging by timer or with constant voltage Charge and when the voltage of the auxiliary battery has become less than 9 V, the battery ECU records this DTC. At the same time, the battery ECU stops charging and displays ERR for 30 seconds on the battery charge panel.

DTC No.	DTC Detection Condition	Trouble Area
C2943/403	Auxiliary battery malfunction	Auxiliary battery
	DC/DC converter malfunction	DC/DC converter

INSPECTION PROCEDURE

CAUTION:

To avoid receiving an electrical shock, observe PRECAUTION on page DI-133.

1 Check auxiliary battery voltage (See page BA-1).

NG Replace auxiliary battery.

OK

Check and replace DC/DC converter (See page DI-57).

2003 RAV4 EV (RM1003U)

Author: Date:

289